


Training for Seaory S series Card Printer


1. Structure Introduction of S series card printers

2. Introduction of Fix Tools

3. Solutions for S series Card Printer Operation Trouble

*Structure Introduction
of
S series card printers(S21)*





Red end ribbon coding sensor


Cam motor

Card feed motor


White end ribbon coding sensor


White end color ribbon drive

ADF card feed
motor
(Reverse card feed
cam)
ADF cam sensor
Magnetic
stripe read
head cam
Ribbon white end
drive motor
card feed motor



Magnetic stripe
module
interface
Contact IC transfer
interface
Original module
interface
Module interface
of Third party
Ribbon red end
drive motor
TPH cam
motor
Contact readhead
cam






ADF card feed motor



ADF card feed motor (reverse card feed cam)

ADF cam mechanism




TPH Cam
Sensors


Print head

Cooling Fan

Ribbon Led




Introduction of Fix Tools



1. Renew the print head
2. Adjust the print head voltage to control the color shades of the print content

Printed cards with colored lines




Ribbon error Code 48 Calibration


Print over edge, white edge, ribbon broken

IC card reading failure Calibration

Contactless Card reading instability adjustment



Test whether the card sensors are in card slots



Test whether the card position sensor is normal

Test sensor of defective card slot


Test whether the card feeding is normal

Check the cooling fan is move or not

Test whether the upper cover button is normal, press and hold the value is 0, release is 255

When the top cover closed, value is 0. while open, value is 255.

Test whether the ribbon lamp is damage



Test the stability of reading and writing values. After writing, consecutive read and write normal, means it is stable, if frequent inconsistencies in write and read data, is abnormal, shall replace the magnetic stripe module to confirm.


*Solutions
for
S series Card Printer Operation Trouble*

Information required


- Picture of failure
- Description of failure
- Production process number, firmware version, driver version



Error Code



Detail Image



Screenshot of driver tool

Failure Solutions

1. *About the Ribbon Failures*

2. *Printing Effect Adjustment*

3. *Card Jam*

4. *Card Feeding/output Failures*

5. *Other Failures*

1. About the Ribbon Failures

Ribbon out- Code 41

Cause: The ribbon chip count is used up, but the ribbon still has a little left.

Solution: Replace a new ribbon




Note: Basically, this problem rarely occurs. More often than not, the ribbon is used up, and there are still one or two prints left in the chip. If there is any discrepancy with the above, please take a photo and send it to our company for confirmation.

Ribbon error- Code 42


Cause 1: The ribbon chip is abnormal and unstable, the counting of the ribbon chip fails to be deducted



Cause 2: RF coil induction instability, the counting of the ribbon chip fails to be deducted



Solution: For error 42, first open the printer driver to check the ribbon information in the tool item, if fail, then cross-verify the ribbon chip and RF antenna. Chip problems to replace the chip, RF antenna problems, replace the antenna.




Ribbon missing- Code 43


Cause 1: No ribbon installed in the printer



Solution: Install the printer ribbon.



Cause 2: The ribbon is installed in reverse



Note: The 2 situations for ribbon installed reverse: 1, The color is not installed in correspondence; 2, The color is in correspondence, but the chip direction is wrong

Cause 3: Ribbon chip damage




Solution: Replace the ribbon and test, confirm whether or not the ribbon chip problem is, replace the ribbon if it was.



Cause 4: RF antenna cable loose or antenna damage

Solution: Confirm whether the ribbon is normal, then check the RF antenna cable, if the cable is normal, replace the RF antenna



Ribbon unsupport- Code 44

Cause: The ribbon code type does not match the printer **Solution:** Please use the ribbon corresponding to the printer code type



Ribbon missing- Code 45


Cause 1: The ribbon is broken



Solution: Remove the ribbon, tape the break with tape, then roll the broken ribbon to the white end



Cause 2: Ribbon shaft gear damage




Solution: Replace the ribbon shaft gear



Cause 3: Ribbon Mask loose


Solution: Adjust the ribbon mask strictly in accordance with the SOP for Install Washers of Ribbon Mask.



Note: The red end of the ribbon is rewind, indicating that the ribbon is not processed after the error 48, and then the self-test will indicate Ribbon missing code 45.

If the motor in pickup/receiving end does not rotate, the red motor will keep rolling the ribbon to the white end during the self-test, causing the ribbon to rewind, and then prompting ribbon error 48. After prompting ribbon error 48, the rewound ribbon at the red end is not recovered, and then when restarting the self-test, the subsequent error will be found as ribbon missing code 45 because the ribbon at the red end is rewound below the ribbon shaft.

Cause 4: The ribbon is off-axis, making it difficult for the ribbon to rotate and make a "cluck" sound




Solution: Remove the ribbon and push it to the center of the ribbon axis

Cause 5: The core board is in poor contact, causing the gear to get stuck

Solution: Re-plug the core board

Note: When the core board contact is poor, Code 48, 49 will also occur.



Ribbon out- Code 46

Cause: The ribbon installed in the printer is used up, but the chip count is still left.



Solution: Replace a new ribbon



Ribbon error-Code 48

Cause 1: Ribbon breaks during printing

Solution: Remove the ribbon, tape the break, then roll the broken ribbon to the white end



Note: If the ribbon breaks often, please refer to the ribbon breakage failure solution


Cause 2: Sensor parameter decay

Solution: Click the Calibrate in the driver tools of the Ribbon Led for correction, the normal light value in 195, 195 or so




Ribbon Led value
 Y: 32, 182
 M: 27, 15
 C: 166, 39
 K: 8, 10
 O: 186,195


Note: When the calibration failed, but the sensor light value is still above 50, then the sensor light gets dirty or the sensor is crooked, and the upper and lower are not aligned. If cleaning and calibration do not work, you need to trigger the corresponding upper and lower two Ribbon Leds for alignment, until the light value returns to normal.



Back




Front




Cause 3: Sensor cable loose or sensor damage


Solution: After the calibration failed and the light value showed 0, check the sensor cable, if the line is no problem then is the sensor damage, shall replace it




Note: The ribbon sensor is divided into Ribbon Led sensor and Ribbon Led, the three light beads above are the Ribbon Led and the three light beads below are the light sensor.



Ribbon Led is on, means it is normal



You can use the phone flash against the corresponding light beads to read the value, the light value can be above 100 is normal.

Cause 4: Ribbon Led bracket deformation**Solution:** wrench the Ribbon Led bracket to the normal angle

Note: The deformation of the Ribbon Led bracket is caused by the artificially misplacing of the ribbon to the bottom of the print head and then press the top cover.



Cause 5: Poor contact with the core board, resulting in gear jams




Solution: Re-plug the core board

Note: When the core board contact is poor, it will also cause the failure code 45, 49




Cause 6: The supply and receiving side end of the motor cable abnormal or motor damage (color ribbon)

Solution: If no problem with the cable, please replace the motor




Causes 7: There are other substances between the gear of the supply end and the receiving end of the ribbon, which causes the stuck(color ribbon)

Solution: Remove other substances from the gears



Cause 8: Washers of ribbon mask(limit gear) loose, continuous gear jumping during printing (color ribbon)

Solution: Continuous “clatter” noise when gear jumping . If you hear this sound, please adjust the clamping piece according to the Washers of ribbon mask adjustment document.





Ribbon error- Code 49

Cause 1: the ribbon drive mechanism is too tight, receiving end(pick-up end) rotation is stuck frequently, or slippage during the transmission process so that the printer determined the color block diameter abnormal.

Solution:


- 1, Check if the ribbon clamping plate is too tight
- 2, Check whether the ribbon gear has broken cogs
- 3, Check whether the printer drive gear is worn or installed too tight.



Cause 2: Poor contact with the core board, resulting in gear jams


Solution: Re-plug the core board

Note: When the core board contact is not good, there will also be code 45, 48 error.





Reason 3: Poor contact of the ribbon sensor wiring and incorrect calculation of the color block length.

Solution: Re-plug the sensor cable



Causes 4: The ribbon type does not match the ribbon chip



Solution: Replace the ribbon



Example: Half-panel ribbon chip is encoded with YMCKO full panel ribbon type

Cause 4: The sensor light value is low (half-panel YMCKO ribbon)



Solution: Calibrate the Ribbon Led



Ribbon Breakage

Cause: The print starting position is too far forward

Solution: Adjust the L+ value of print starting position through position calibrate in the driver tool



Note: The reason for ribbon breakage needs to be integrated with the card and ribbon breakage at the trace to determine, while the direction of the color block break is near the print starting end of white end, the print starting position is too far forward.

Cause 2: Repeated printing the same card



Solution: Make sure the card is printed repeatedly, please use a new blank card for printing




Note: It is not recommended to reuse the card that has been printed (even the card is still blank). The content is not printed on, does not mean that the laminate layer is not covered, it can be judged through the ribbon print traces.

Cause 3: Abnormal ribbon tension

Solution: Adjust the clamping plate of ribbon axis mask strictly accordance with the Washers of ribbon axis mask document




Note: The abnormal ribbon tension is usually caused by artificially adjustment if it is serious. You can remove the top cover to observe the tension state of the ribbon during the printing, the ribbon should not be too loose or too tight.



Cause 3: Print head bracket broken**Solution: Replace the print head bracket**

Note: Print head bracket breakage is usually caused by the ribbon up shrapnel failure so that the ribbon collapse, when the top cover closed, the print head would be crushed due to ribbon resistance deviated from the guide slot on both sides of the print head



Cause 4: Ribbon LED bracket deformation




Solution: Wrench the Ribbon Led bracket to the normal angle, re-roll the broke ribbon in good condition



Note: The deformation of the ribbon LED bracket is caused by artificially misplacing the ribbon bellow the print head and then press hard the top cover.





Cause 5: Dirt in the cam sensor**Solution: Clean the cam sensor**


Note: Dirt in the cam sensor will cause the sensor to misjudge the position of the cam mechanism, resulting in abnormal downward or upward pressure on the print head when printing

Cause 6: Printing temperature is too high

Solution: Reduce the value of heating energy




Note: The heating energy value is not correct, usually due to the when replacement of the print head with not replacing the print head barcode, please enter the replacement print head barcode in the driver




2. Printing Effect Adjustment

Discoloration / Abnormal streaks / Other
wrinkles


Cause 1: Abnormal ribbon tension causes some abnormal streaks at the beginning or middle of the printing



Solution: Driver: Print Option - Tools - Ribbon Tension Adjustment - Red End (-)




Note: Abnormal printing caused by abnormal ribbon tension, we can find abnormalities in the ribbon traces, such as the wrinkles traces on the ribbon in the picture below.



Cause 2: Abnormal ribbon tension causes wrinkles when laminating



Solution: Drive Print Option - Tools - Ribbon Tension Adjustment - White End (+)




Note: It can also be solved by reducing the O-layer heating energy.

Cause 3: Abnormal ribbon tension causes wrinkles at the edge of card when laminating




Solution: Driver: Print Options - Tools - Ribbon Tension Adjustment
- Red End (+)



Cause 4: Abnormal ribbon tension causes color patterns at the edge of card

Solution: Driver: Print Options - Tools - Ribbon Tension Adjustment - Red End (+)




Note: There is another situation that causes color patterns at the edge of card when the ribbon is off-axis, so pay attention to it when checking.



Cause 5: The ribbon tension abnormalities causes horizontal lines on image




Solution: Driver: Print Option - Tools - Ribbon Tension Adjustment - Red End (+) White (-)



Cause 6: Abnormal ribbon tension causes a serious mess on images

Solution: If it occurs without adjusting the clamping plate, please check if there is any other substances in the gear mechanism



Note: Severe messy pattern is usually caused by improper adjustment of clamping plate artificially. If the clamping plate has not been moved, then there are some substances dropped into the ribbon drive gear or TPH cam gear, which causes the gear to rotate abnormally.


A blank vertical line running through the card

Cause 1: Dirt or broken needle of the print head


Solution: clean the print head first, if failed, you need to replace the print head



Cause 2: The print head signal line damage or poor contact



Solution: Replug the wiring cables again and check if the wiring cable communication is normal



Note: This failure is somewhat similar to the print head needle broken, but it does not usually appear such a wide blank vertical lines at the first time, you can check the specific print head to distinguish.

Skewed Print

Cause: The print head has a slight offset during the printing process

Solution: Remove the guide slot with the shrapnel, add a washer of about 0.5mm shown as the red circle and lock it back.



Print slippery with yellow blocks


Cause 1: Ribbon gear wear




Solution: Replace the ribbon shaft gear



Cause 2: Washers of ribbon axis mask loose



Solution: Adjust the Washers of ribbon axis mask strictly in accordance with the SOP for Install Washers of ribbon axis mask




Print blank cards

Cause 1: The starting end of the print is out of range of the card and prints to the cam




Solution: Driver - Tools - Print Position Calibration - Adjust the "L+" value.



Cause 2: The task sent is abnormal and transmits blank information to the printer

Solution: Check whether there is any abnormality in the transmitted content, you can change another method to print and verify




Color printing unpositioning



Cause 1: The starting end of the print is out of range of the card and prints to the cam



Solution: Driver - Tools - Print Position Calibration - Adjust the "L+" value.



Note: The limit of the margin adjustment of the printing end will increase the possibility of the ribbon printing on the CAM, and the judgment method is to view the print trace on the ribbon, and it can be clearly seen that the print trace on the ribbon has the grain on the CAM.

Cause 2: Dirt on TPH cam sensor**Solution: Clean the TPH cam sensor**

Note: Dirt on the TPH cam sensor will cause the print head to not press down onto the card properly when printing because the sensor misjudges the position of the cam mechanism.

Defective printing & Unclear printing

Cause 1: Uneven surface of the card causes the defective printing

Solution: replace a new card and reprint



Cause 2: There is ink on card surface while printing with no lamination, resulting in unclear printing

Solution: Please replace the card with a laminated film to print.



Cause 3: Abnormal ribbon tension causes defective printing

Solution: Adjust the ribbon tension red (-)



Note: There is also a situation where the ribbon is off-axis, so pay attention to it when troubleshooting.




Cause 4: Repeated printing of color ribbons


Solution: Stop repeating to print the same side of the card



Note: The printed blank cards should not be used again, although there is no content printed on, it does not mean there is no lamination.

3. Card Jam





Card jam caution when cards in printer:

- 1.The card is still keep in the printer after printing finished. When the printer is reset, the card in the machine is detected and the card jam is reported.
2. A card is inserted into the printer before it is dispensed, and the self-service kiosk is removed every day when the staff gets off work. Next day the printer will be reported the card jam.
3. The ribbon tension is abnormal, and the ribbon adheres to the card when printing, causing the card to move off the track or get stuck in the track.
4. Repeated printing of the card may cause the ribbon to stick to the card, causing the card to move off the track or get stuck in the track.
5. The cards overlap into the printer.

Card jam caution when no cards in printer


- 1.The use time of the printer is too long, or the use of the environment is too dusty, and it is not cleaned on time, resulting in the accumulation of a lot of dust at the sensor, which affects the normal work of the sensor.
2. In the process of card dispensing, the sensor line contact is poor, and the vibration will cause misjudgment.
3. The broken pieces of the ribbon falling to the sensor while printing.

Soltion:

Please deal with it according to the corresponding failure case. If the Card jam does not match with the above situation, please provide the detailed card issuing process, failure log, jamming photos and videos of the site to our company for confirmation.

Causes:

Card jam 10	1、The card is out of track in the process of card walking, and the sensor does not detect the card; 2、Poor contact of the sensor line, the vibration generated by the rotation motor makes the sensor misjudged
Card jam 11	1、P1 sensor card jam; 2、P1 sensor dirt or foreign objects; 3、P1 sensor's cable is abnormal; 4、P1 sensor damaged; 5、Cleaning wheel or spring comes off (S22K and S22, S22M)
Card jam 12	1、Card jam at Card input month (P1) or card flip point (P6); 2、dirt or foreign object, sensor's cable is abnormal, sensor damaged (Probability is almost 0)
Card jam 13	1、card jam at card flip point (P6); 2、dirt or foreign objects at card flip point (P6); 3、card flip point (P6) damage
Card jam 14	1、Turnover device (P6) and card moving roller (P2) have card jam; 2、dirt or foreign object, sensor's cable is abnormal, sensor damaged (Probability is almost 0)
Card jam 15	1、P2 sensor card jam; 2、P2 sensor dirt or foreign objects; 3、P2 sensor's cable is abnormal; 4、P2 sensor damaged
Card jam 16	1、P3 sensor card jam; 2、P3 sensor dirt or foreign objects; 3、P3 sensor's cable is abnormal; 4、P3 sensor damaged
Card jam 17	1、card jam in P3+P4 sensor; 2、dirt or foreign object at P3+P4 sensor; 3、abnormal cable of P3+P4 sensor; 4、P3+P4 sensor damaged (Probability is almost 0)
Card jam 18	1、Card jam or ribbon at the card exit mouth sensor (P3+ P4 +P5 OR P4+P5); 2、P3+P4+P5&P4+P5 sensor cable abnormal; 3、P3+P4+P5&P4+P5 sensor abnormal (Probability is almost 0)
Card jam 19	1、card jam at P5 sensor; 2、dirt or foreign object at P5 sensor; 3、abnormal cable of P5 sensor; 4、P5 sensor damaged
Card jam 1B	1、P4 sensor is damaged or foreign objects.; 2、P4 sensor's cable is abnormal; 3、P4 sensor damaged
Card jam 1A	Card jam or something jam between not the nearest two group sensors



4. Card Feeding/output Failures

Introduction of card feeding error code corresponding to the direction of card feed

Card feed error - Code51



Front end

Card feed error - Code52




Back end

Card feeding Error-Code51

Cause 1: Wrong setting of the direction of the card feed, such as the back-end card feed, while set the auto card feed from the card feed slot in the driver



Front end




Back end


Cause 2: Improperly set the card feed scale



Solution: Please set the correct card feed direction.





Solution: Please set the card feed scale according to the thickness of the card



Cause 3: Card feed motor damage or cable loose


Solution: First check whether the card filpper can rotate or not, if failed please check the motor wiring first, otherwise that is the problem of motor damage, and needs to be replaced.



Cause 3: The cards are stuck together by static electricity so that the card feeding failure



Solution: Spread out the cards and let cool for a while before using.



Cause 4: The card deformation resulting in insufficient roller contact card area



Solution: Remove the deformed cards and leave the normal ones



Card feeding Error-Code52

Cause 1: The direction of the card is set incorrectly, for example, the card feed by front end of printer is set to the card feed by rear end in the driver



Front end




Back end

Cause 2: external factors lead to the inability of card feeding




Solution: Please set the correct card feed direction.




Solution: Please check the external factors, such as the carriage is not aligned with the printer

Cause 3: Card feed motor damage or wiring loose




Solution: When moving the card, the moto does not turn, and the wiring should be replaced if there is no abnormal



Causes 4: Card feed mechanism gear jammed or belt broken




Solution: Check if the belt is broken, check if there is any other substances jammed between the gears




Card output - Error Code 5F


Cause 1: No cards in card slot



Solution: Put the cards in card slot



Cause 2: The yellow no card detection rob fall off



Solution: Put the yellow no card detection rob back



5. Other Failures



ADC Error- Code 2

Cause 1: Abnormal print head cable

Solution: If the print head cable is not broken, please re-plug the cable

Cause 2: The previous firmware 0.12.72 execution appears when there is a card reset

Solution: Update firmware to 0.12.74 and above



Ribbon supply end error- Code 4

Cause 1: The ribbon supply side of the sensor wiring is loose or sensor damage (color ribbon)





Solution: Check whether the wiring is abnormal, if working, replace the sensor




Ribbon receiving end error- Code 3

Cause 1: Ribbon supply end, receiving end drive gear jammed **Solution:** Clear the dust or debris from the gears (black ribbon)





Causes 2: The ribbon supply side (black ribbon), the receiving end of the sensor cable is loose or sensor damage


Solution: Check whether the cable is abnormal, if working, replace the motor



Causes 3: the ribbon receiving end of the motor cable abnormal or motor damage (black ribbon)



Solution: Check whether the moto is abnormal, if working, replace the motor



Top cover open- Code 21


Cause 1: The top cover sensor lining abnormal or sensor damage



Solution: If no abnormal wiring occurs, cleaning the sensor is invalid. Replace the sensor




Cause 2: The switch sensing mask on the top cover is broken





Solution: Replace sensing mask



Defective card box open- Code 22





Cause 1: Defective card box open



Solution: Close the defective card box



Cause 2: The defective card box sensor wiring is loose or sensor is off

Solution: If no abnormal wiring occurs, move the sensor about 2mm in the direction of the defective card box..



Defective card box full- Code 23

Cause 1: The defective card box load more than 30 cards.



Solution: Take out the cards




Cause 2: Cards in the defective card box are not moved into right place which causing a blocking the sensor



Solution: Take out the cards




TPH CAM error- Code 31




TPH cam
sensor

Cause 1: Dirt or damage on the cam sensor



Solution: Clean the cam, if failed, replace the sensor.




Cause 2: The CAM motor wiring is abnormal or the motor is damaged



Solution: The motor does not rotate during the boot self-test, please check whether the wiring is normal, if no problem with the wiring, replace the CAM motor



Cause 3: The gear of the CAM mechanism is stuck by some other substances.



Solution: Remove other substances from the cam mechanism gears






Cause 4: The power adapter is not original which causing the insufficient power supply

Solution: Please use the original power adapter



ADF CAM error- Code 32





P1 sensor
ADF cam
sensor


ADF card feeding motor



ADF cam
mechanism

ADF card feeding motor
(reversing card feed cam)

Cause 1: ADF sensor cable is loose



Solution: Re-plug the ADF sensor cable





Cause 3: Damage of the ADF sensor




Solution: Replace the ADF sensor

Cause 3: ADF motor sensor contact is poor or motor damage **Solution:** Re-plug the ADF motor cable, if failed, replace the motor





Card Flipper error- Code 33




Cause 1: Poor contact of card flipper motor cable or flipper motor damage which resulting in the flipper can not flip and positioning.

Solution: Re-plug the motor cable, if still failed, replace the motor



Cause 2: Poor contact with the sensor cable or sensor damage, resulting in card flipper alignment failure





Solution: re-plug the sensor cable, if failed, replace the sensor




Cause 3: The black masking piece on both sides of the flipper broken


Solution: Replace the card flipper mechanism



Authentication Error- Code 62

Cause 1: Poor connect of PSAM card**Cause 2: The motherboard PSAM card circuit chip burned out****Solution: Clean the PSAM card**

Solution: If the firmware is 0.12.66 and below, before the failure, please upgrade the firmware 0.12.68 and above; The motherboard has been broken, go through the after-sales process to repair



No response when power on

Cause 1: Damage of the adapter




Solution: Replace the adapter




Cause 2: DC power interface or motherboard damage

Solution: Required for an after-sale service



Display does not show text

Cause 1: Poor contact with the display wiring



Solution: Remove the wiring again. If the failed, weld the bottom wiring

Cause 2: Damage of the display



Solution: Replace the display



Abnormal communication between the
printer and the computer

Cause 1: Abnormal computer USB interface

Solution: Replace the USB interface (it is recommended to use the rear interface)




Cause 2: Use non-original USB cable, or USB adapter device connection

Solution: Please use the original USB cable to connect directly to the computer




Abnormal communication between the printer and the computer


Cause 3: Uncorrect driver version




Solution: Update the driver to version 0.9.27.0 or above



Cause 4: Abnormal shutdown of the printing service




Solution: Restart the print service



Cause 5: Completely unresponsive when printer connected to the computer

Solution: change another computer to confirm whether it is the problem of computer, if it is the same result after several attempts, it determined the printer motherboard damage, return it to the factory.




Module cannot be connected

Cause 1: Abnormal or poor contact of the cable



Solution: If no abnormalities of the cable, re-plug



Cause 2: Module damage or firmware abnormal



Solution: If failed again after updating the firmware, replace the module

	config	2020/11/20 13:58	配置设置 1 KB
	GeneralReader.dll	2018/5/16 16:53	应用程序扩展 225 KB
	t10fwupdate	2018/5/16 16:53	应用程序 32 KB
	T10SE1.SER.0101.DC4.SVN26.201120.drv	2020/11/20 14:47	设备驱动程序 123 KB

Thank you